CORE ANALYSIS OF PORTLAND CEMENT CONCRETE SLIP FORMED BARRIERS

Final Report For MLR-98-4

January 2000

Highway Division





Core Analysis of Portland Cement Concrete Slip Formed Barriers

> Final Report for MLR-98-4

By Robert Steffes Assistant to the Research Engineer 515-239-1392 FAX 515-239-1092 and Todd Hanson P.C. Concrete Engineer 515-239-1226 FAX 515-239-1092 Office of Materials Project Development Division Iowa Department of Transportation Ames, Iowa 50010

January 2000

TECHNICAL REPORT DOCUMENTATION PAGE

REPORT NO.	2. REPORT DATE	
MLR-98-4	January 2000	
3. TITLE & SUBTITLE	4. TYPE OF REPORT & PERIOD COVERED	
Core Analysis of Portland Cement Concrete Slip Formed Barriers	Final Report, 10-98 to 9-99	
AUTHOR(S)	6. PERFORMING ORGANIZATION ADDRESS	
Robert Steffes	Iowa Department of Transportation	
Assistant to the Research Engineer	Materials Department	
and	800 Lincoln Way	
Todd Hanson	Ames, Iowa 50010	
P.C. Concrete Engineer		
C C		

ABSTRACT

Premature deterioration of slip formed portland cement concrete (PCC) barriers is an ongoing problem in the Iowa Primary and Interstate highway system. The requirement to have a concrete mix which can be sufficiently pliable to be readily molded into the barrier shape and yet be sufficiently stiff to maintain a true shape and height immediately after molding is difficult to meet. A concrete mix which is stiff enough to maintain its shape immediately after molding is usually difficult to work with. It often contains open or hidden tears and large voids. One way to minimize the molding resistance is by additional vibration. If intensive vibration is applied, the entrapped air voids and tears in the concrete can usually be eliminated, however, in that process, the essential entrained air content can also be lost. In the evaluation of slip formed PCC barriers, it is common to find large voids, tears and a low entrained air content, all contributing to premature deterioration.

A study was initiated to evaluate core samples taken from good and from bad appearing areas of various median barriers. Evaluations were done covering visual appearance, construction information, air content and chloride content.

63

8.

TABLE OF CONTENTS

Pag	ge
Introduction	1
Objective	1
Project Sites	1
Core Descriptions	1
Results	1
Conclusion	2
Implementation	3
Acknowledgment	3
AppendicesAppendix A - MLR ProposalAppendix B - Concrete Median Barrier Standard PlanAppendix C - Project Sites, Contractors and Field NotesAppendix D - Core DescriptionsAppendix E - Core PhotosAppendix F - Core Analysis TablesAppendix G - New Mix Design for Concrete Barrier Rail	8 . 10 . 44 . 46 . 58

DISCLAIMER

The contents of this report reflect the views of the author and do not necessarily reflect the official views of the Iowa Department of Transportation. This report does not constitute any standard, specification or regulation.

INTRODUCTION

Some PCC median barriers showed signs of having less than desirable qualities in appearance and durability. To achieve the desired molded shape, excessive vibration was often applied to a stiff concrete mix. The finished product was sometimes a barrier with large entrapped air voids, tears and low entrained air content, all contributing to premature deterioration. A Materials Laboratory Research proposal, MLR-98-4 (see Appendix A) was set up to evaluate the problem.

OBJECTIVE

The objective of the research is to evaluate existing PCC median barriers and to find procedures, materials and mix designs which will result in a better appearing, more workable and more durable PCC slip formed median barrier.

PROJECT SITES

The sites for taking median barrier core samples were selected to cover four different construction projects. They were all from Interstate routes in Polk County (see Appendix C). With careful observations in the field, the exact location of the core sampling sites may be visible by the evidence of filled core holes.

CORE DESCRIPTIONS

Cores were taken from the median barrier of I-80 in Polk County, October 1998. The core description, "bad," means there was significant visual appearance of barrier surface deterioration, i.e., cracking, staining and leachate deposits. The core description, "good," means there was no visual appearance of deterioration on the barrier surface.

The arrow on the face of each core points to the top position. This position was marked to determine if core voids, cracks or tears show a relevance to direction of paving.

The core sites were selected such that no reinforcing steel should be hit by the coring bit (see Appendix B).

RESULTS

The search for information and construction history for the selected sites gave limited success. The majority of information came from field book notes which often gave minimal details. For project sites, mainly 1 and 3, air content problems were recorded a number of times (see project diary and

daily reports, Appendix C).

The visual appearance of some cores showed major voids or tears within the concrete as a result of construction workability, consolidation or mix design problems (see photos, Appendix E).

The results of coring from some areas of barriers with a bad appearing surface showed no significant "bad" problem deeper into the barrier. Examples are core photos 1A and 1C. In other cases, large voids or tears were exposed during coring which were not detectable from surface visual examinations (see core photos 2A and 2B). The concrete in core 4B was so deteriorated that it could not be prepared for laboratory analysis. The air system for most cores was found to be acceptable except for core 1A (see appendix F).

From the differences in core conditions and surface appearances found, it can be seen that there is a wide range and somewhat unpredictable quality of concrete to be found in the barriers.

CONCLUSION

As a result of the study of median barrier quality problems, a significant amount of work has been done to change the mix design to something which would be more suitable for slip formed barrier applications.

The standard Iowa DOT D-57 mix design has typically been used in slip formed barrier rails. This mix has a high amount of paste and fines, having a cement content of 709 lbs./cu. yd., with 50% coarse aggregate and 50% sand. The typical combined gradation produces a gap-graded aggregate structure and in conjunction with the high paste content it produces a very stiff unworkable mix.

In 1999, slip formed barrier rails were being placed on the dual bridges over the railroad on relocated US 18 in Floyd County, near Rudd. The contractor, Allied Construction, called in with problems concerning entraining air in the D-57 mix. The D-57 mix is typically placed at 3/4 in. slump making it difficult to entrain air. The producer had been using 25 oz./cwt of air entraining agent and was able to achieve only 5.5% plastic air content. It was decided to investigate the use of well-graded aggregates in conjunction with a reduced cement content to facilitate placement and air entraining of the concrete.

The new mix design for the concrete barrier rail (BR) utilized well-graded aggregates through the incorporation of ¹/₄" (6.35 mm) chips and a reduced cement content of 603 lbs./cu. yd. This mix required only 8 oz./cwt of air entraining agent to achieve 7.4 % plastic air content. They were also able to increase the slump to 1 in. and rate of placement was increased.

Since this project, the BR mix was included in the standard specifications. In the fall of 1999, it was used on a median barrier on I-35/80 in Des Moines from Merle Hay Road to the 2nd Avenue interchange. The BR mix design achieved better placement characteristics and air entraining

capacity than the D-57 mix design.

Additional design adjustments may be needed as material and construction conditions vary. From initial applications, the new mix design appears to be a significant improvement over previously used mix designs. The new mix design specification for BR is now being applied (see Appendix G). At this time, no specific recommendations for changes in vibration energy applied or configuration of vibrators will be made.

IMPLEMENTATION

A major effort has already been put into place to develop a new concrete mix especially designed for use in slip formed barriers. Initial use of the new mix occurred in 1999 in bridge barrier rails in Floyd County on US 18 and in median barriers in Polk County on I-35/80.

The new mix design was already found to be easier to work with and will result in a better finished product.

ACKNOWLEDGMENT

Sincere thanks and appreciation goes to the Special Investigation personnel for their support to obtain core samples and to the Cement and Concrete personnel for their support in the core analysis.

APPENDIX A MLR Proposal

DATE: October 28, 1998

PROJECT: MLR-98-4

TITLE: Core Analysis of Slip Formed Barriers

PRINCIPAL INVESTIGATOR: Todd Hanson and Bob Steffes

- **OBJECTIVE:** The objective of this research is to determine the air content and void system of low slump Portland cement concrete (PCC) slip formed median barriers in search of causes of premature concrete deterioration.
- **DISCUSSION:** In some areas of some slip formed barrier projects, premature deterioration appears to be occurring. Extensive surface cracking and growth of leachate deposits become visible on the barrier surface within a few years after construction. To slipform a barrier, a relatively dry, stiff mix of concrete is required and extensive vibration is used to facilitate concrete consolidation and forming. It is assumed that an inappropriate mix design for the application and/or excessive vibration may be contributing to the premature deterioration.
- **PURPOSE:** The purpose of this study is to determine if adjustments in mix design, vibration for consolidation or construction techniques could be made which would result in an improved appearance and durability of slip formed PCC barriers.
- **PROCEDURE:** Cores will be taken from median barriers from four different paving projects on I-80 and I-80/I-35 in Polk County. Core sites will be selected to include areas with no visible deterioration and sites which show extensive deterioration. The cores will be 4" diameter and approximately 5" long, perpendicular to the barrier face. They will be taken approximately 30" above the roadway surface.

ANALYSIS: The core analysis will include chloride content at various depths, and a detailed determination of the air void system.

The chloride contents will be checked at 0.5", 1", and 2" intervals using the Phillips XRF. Samples will be analyzed for elemental chlorine (Cl) and used to estimate the amount per cubic yard.

Air content will be checked at 0.5" and 1" intervals using the Hitachi low vacuum SEM in conjunction with an image analysis program. The air content (%), specific surface (α), and spacing factor (L) will be calculated at each depth.

Records of concrete mixes used and construction logs will be evaluated, if core analysis results are found to be abnormal.

RESPONSIBILITIES: Projects for evaluation will be selected by the Portland Cement Pavement Engineer.

Specific sites for cores will be selected by the Materials Research personnel.

Coring will be done by Special Investigations personnel.

Analysis of cores and summation of results will be done by the Technical Services Engineer.


IMPLEMENTATION: The findings from this study will lead to:

1) Improvements in the concrete mix design, workability, durability and appearance of the barriers.

2) Improved consolidation while still maintaining desired entrained air content.

REPORTING: The final report will be coauthored by Todd Hanson and Bob Steffes.

APPENDIX B Concrete Median Barrier Standard Plan



APPENDIX C Project Sites, Contractors and Field Notes

PROJECT SITES, CONTRACTORS AND FIELD NOTES

<u>Site 1</u> Site Location:

I-80 East bound lane MP 139.05, MP 140.06 Paved west to east Used D-57 1994

Contractor:

Dormark Construction Company P.O. Box 520 303 S 2nd Street Grimes, IA 50111 515-986-4270

Field Notes:

See pages 13-22

Site 2 Site Location:

I-35/I-80 West bound lane MP 132.90 Paved west to east Used D-57-C20 & D-57-C10 1998

Contractor:

Jensen Road Company Box 3345 5550 NE 22nd Street Des Moines, IA 50316 515-266-5173

Field Notes:

See pages 23-31

PROJECT SITES, CONTRACTORS AND FIELD NOTES, Continued

<u>Site 3</u> Site Location:

I-35/I-80 West bound lane MP 128.25 Paved west to east Used D-57 & D-57-6-C 1994

Contractor:

Jensen Road Company Box 3345 5550 NE 22nd Street Des Moines, IA 50316 515-266-5173

Field Notes:

See pages 32-43

Site 4 Site Location:

I-35/I-80 South bound lane MP 126.50 Files have been purged Paved south to north

Contractor:

United Contractors Inc. P.O. Box 347 6678 N W 62nd Avenue Johnston, IA 50131 515-276-6162

Field Notes:

Field notes were purged

Site 1

	Page of
DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
10-17-94	
MONDAY	RAINING MOST OF THE DAY, NO ONE
·	WORKING - GETTING BOOK WORK CAUGHT UP.
	l
10-18-94	
 	LIGHT ROW SHOWER THIS A.M. EARLY PET
	LIGHT ROW SHOWER THIS A.M. EARLY, PET WORKHAK ON GRODING MED. (FORME ACCOUNT) AND PAVING MEDIAN, 6
	! MEDIAN, 6
	WINMOR POURING GTOPS THIS MORNING 8:30 TO 1200
	AND WILL TRY FOR Z OR 3 MORE IN AFTER MOON
	DORMARK SETTING UP FOR SLIP FORM BARRIER WALL,
	WILL GET STARTED AFTER Noop! WORKING UNITY
*	ABOUT GOD. SOME PROBLEMS WITH CONCRETE - GETTING
	ALR. CONTENT UP IN MIX AND REEPING IT THERE
	FULLISHED FORCE ACCOUNT ON WEBLAN GRADING.
	\longrightarrow
	13

FORM IE Page____ of ____

CONTRACT DIARY PROJECT NO. WEATHER/COMMENTS DATE ! 10-19-94 CLAR NED POIL POURING MEDIAN AND REMAINED BOXOUTS. PET ALSO SEALING WEDIAN PAYEMENT. WINMOR BUILDING INTAKES WILL POUR THIS AFTER NOON DORMARK SETTING UP MACHINE FOR SLIPFORM RAIL. STARTED RUNNING . 11:00 A.M. FINISHED LENGTH WEST OF 29th ST. 3:30 DONE FOR THE : DAY, 4:30 WINMOR STARTED POURING TOPS FOR INTAKES 17, 18, 19, 20, 21 Doute 6:30 10-20-94 PET FINISIED WITH MEDIAN PAVING AND URSON! WITH REMOVING BOXONTS - DRILLING DOWELS DORMARY WORKING ON SLIPFORM WALL AND FORMULLO ON CASTIN PLACE, STILL REMIND PRODUCING * WITH ANR (ENTRANCED AIR) IN CONC. RUNNING LOW. WINMOR WORKING ON INTOKE TOPS. 14

FORN IE

Page	of	100000000000000000000000000000000000000

DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
10-21-92	
FRIDAY	POT SAWING HAD SEALING ON MEDIAN PAREMENT THIS MORNING.
	WINMOR WORKING ON INTAKE TOPS WILL POUR IN
	AFTER NOON.
*	DRIMBER WORKING BARRIER WALL - SLIPFORM AL DAY STILL HAVING PROBLEMS WITH ENNRHMED
	A.R.
10-22-94 SAT	
	DEMARK HAVING AN KINDS OF PROBLEMS
	WTH GNA TRUCKS AND MUX - SHOT DOWN N'30 AM
	!
	l
	15

FORM 1E Page____ of ____

DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
10-24-94	HIGH 50 LOW 28°
_MONDAY	
*	9:00 MET WITH PETERSON (ONST. ING ABOUT OVER HEAD
	TRUSSES AND DISCUSSED PEOBLEMS WITH OUTSIDE FOOTINGS
	FORECUST COLO ENOUGH FOR COVERING BARRIER
	WALL TONIGHT
10-25-94	NIGH 52 LOW 26
TUESDAY	DORMARK WORKING ON WALL MOAIN SAME
	WINMOR WORKING ON INTAKE TOPS
	MET WITH EIN OF ALTOONA TO DAY TO
	DISCUSS PATCHING HAUL ROAD SECTION OF ADVENTURELAND
	Reiny STARTED REMOVAL OF WB WEIGH STATION
;	16

FORM IE Pade____ of ____

DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
10-2694	HIGH 55 LOW 40°
NEO	WINMOR FINISHING UP ON INTAKE TOPS (3)
	AND WILL FINISH GROUTING PIPE IN INTAKES.
	THAT THEIR HEADER LOCATIONS ARE WRONG IN RELATION
	THE TRANSITION BLOCKS FROM 2- & WALLS TO FUEL
	Ren. Some REMOVE WILL BE NEEDED. MEAS, PART OF 6' MRDIAN 1224 TO 1286
18-27-9el	
THURSDAY	WIN MOR STRIPPING LAST 3 INTAKES MAND GROUTING
	RIPES THUS MORNING, THEN THEY WILL BE OUT OF HERE
	FORMARY WORKING ON SLIPPED WALL AND
Derbalantan he	JUNCTION BOXES FOR CONDUIT ALSO.
	!
	17

FORN 1E Pade____ of ____

PROJECT NO CONTRACT
WEATHER/COMMENTS
VERY WINDY HIGH 69° LOW 48°
DORMARK WORKING ON SLIP.FORM
BARRIER WALL, STARTING AT 7:30 THIS A.M.
AFTER HE HAD TALKED WITH MARK TRUEBLOOD
ABOUT COREING OUR 61 MEDIAN PRIEMENT
MARK SAID WITH WALL WE WONLDN'T HAVE TO
LORE, ALSO HAVE THE GRADE CHECKS FOR VERIFICATION.
RELLY WORKING ON DIRT WT (DIRCH)
OU WE WEIGH STATION ALREADY HAVE REMOVED
BROMG AND SCAR PIT.
DORMARK WORKING ON BARRIER WALL
DON MERKER CALLED ME AT HOME TO DISCUSS
THE TEST RESOLTS THEY WERE GETTING AND FINALLY
THE MATCRIAN STARTED GETTING BEFER.
MITCH TILLAVA CALLO ME AT HOME TO TALK
BBOUT POURING OVER NUSEALED SLAB , ITOLD HIM I
DIDNOT GIVE PERMISSION HE SAND HE WOULD THINK ABOUT IT
DECIDED to LET THEM ROPE AND TAPE ENOUGH TO FILISH
OUT SATURDAY.
<i>i</i>
$\sim \sim $

FORN IE Page____ of ____

DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
10-31-94	
Monpay.	
	REDIAND "E" JOINTS, RET WILL ALSO BE DONNG PATCHING ON HAVE ROAD.
	ADVENTURE LAND DRIVE, TUESDAN
	DORMARK RUNNING WITH DARRER WALL -MGD.
	AND HALF WALL QEZ9THST. Den 1 OKWE DET 1 CIT I DI 151/4
	STATION ALL DAY
<u>_11-1-94</u> TUES,	POE PATENHUL HAUL ROAD TODAY
	al outside Lanes,
	DORMARK WORKING ON SUPPED WALL, MAD
	HALF WALL ON WEST SIDE OF EAST 29 151
	BRIDDE MILLUDING DNE TRANSITION BLOCK REILY WORKING ON WB WEIGH STATION -
	CLEANING IT UP.
	19

FORN IE Page____ of ____

DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
11-2-94	
WED	REILY WORKING ON WEIGHSTATIONS BOTH ER
	PART WB.
	PET WORKING ON SEPTIME AND PATCHING
	HAUL ROAD - ADVENORVELAND FROME
	ANF WALL AND SECTIONS OVER INTAKES,
11-3-94	
THURS.	RE SERVING AND RELLY WORKING ES LOIFGH
	STATIONS
	DORMACK WORKING ON WALL AGAIN TODAY
	STAFTED RAINING AROUND 12:00 SHUT DOWN ROR THE
	processon.
	!
-	
	MS
	20 20

FORM 1E

Page____ of _____

DIARY	PROJECT NO	CONTRACT
DATE	!	WEATHER/COMMENTS
1-1-91		HIGH 50° Low 40°
FRADAY.	- RAINING	FODAY - NOTHING PRODUCTIVE ON
	•	
	OUT AT RI	
11-5-94	<u> </u>	HIGH 46° LOW 35°
SAT	!/	
		NORKHIG TODAY ON BOTH FULLAND
	1	EVERYTHINKS RUNNING WELL, SHUT OFF
	5:30	100 AM , COVERED AND OUT BY
		, A
		VV/
i		21

Daily Report

Contract No.	77-0353-069	Date : We	dnesday, May 27, 1998	Initials of Inspector:	RJE
High Temperat	ure: <u>80.0</u> 5:46 AM	Low Temperature:	65.0 8:38 AM		
	nent: Partly sunny,wa				*
Site Timecha	rge				
00 1.0	00				

Remarks:

Wed-Jensen began slipforming the 42" concrete barrier wall RE-44A Today beginning at 11:15 am. The barrier was begun at 831+50 heading east with only about 350 feet being completed today due to minor problems such as inconsistent slump in the mix which caused the wall to have minor sags and repairs required. The superinendant was Randy Friel for jensen with Norm as the lead foreman on the project. Rod Edwards,Michael Dean and Tom Uppena will handle the inspection on the project. Kevin Merryman, John Rullman, Mitch Dillavou, Mark Trueblood and John Adam all visited the project today from the DOT. Kurt Rasmussen , Dan Timmons and Jeff Rasmussen all visited the project today from Jensen construction co.

KDM - I spoke with Mark Bare today and told him that we need to get as much permanent seeding done on the project as we can. I also told him that we would like to install some more silt fence if possible. The storm water reports for this project will reflect our conversation.

Inspector

Printed 6/14/99 09:40:55 09:40:55

lowa Department of Transportation

Daily Report

Contract No.	77-0353-069	Date :Th	hursday, May 28, 1998	Initials of Inspector:	RJE
High Temperatu	ıre: 87.0	Low Temperature:	65.0		
Sunrise	5:45 AM	Sunset	8:39 PM		
Weather Comm	ent: Sunny, hot and h	numid			
Site Timechar	ge				
00 1.00	00				

Remarks:

Th-Jensen continued slipping the Permanent barrier wall in the median today. Only 300 feet was poured today because the wall had to be set up on the next section east of the Des Moines river bridge. The headers at the drains need to be set and the dowels need to be installed. The concrete tests all complied today with the only problem being the inconsistency of the Mix slump causing tearing of the barrier which all was repaired with no problems. Mark Bortle visited the project today from the dot. The pouring was completed by 12:30 pm with sawing and prep work being performed in the afternoon.

Printed 6/14/99 10:05:19 10:05:19

lowa Department of Transportation

Daily Report

Contract No.	77-0353-069	Date :Tue	sday, June 9, 1998	Initials of Inspector:	TPU
High Temperat	ure: 72.0	Low Temperature:	56.0		
Sunrise		Sunset			
Weather Comm	nent: Rain in a.m., Cle	ear in p.m.			
Site Timecha	rge				
00 0.5	00				
Subcontra	ctor	No			

ID	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen started slipping wall at 10 a.m. due to rain in early morning. New paver didn't work well, switching back to old paver. Mitch stopped by today. Contractor will be switching mix design tomorrow.

Printed 6/14/99 10:07:15 10:07:15

Iowa Department of Transportation

Daily Report

Contract No.	77-0353-069	Date : Wedne	esday, June 10, 1998	Initials of Inspector:	TPU
High Temperature	: 73.0	Low Temperature:	53.0		
Sunrise		Sunset			
Weather Commen	t: Pt. Cloudy				
Site Timecharge					
00 1.000					

bcontracte		
ID	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen started slipping rail at 11:30 with new machine. Worked until 6:00. New mix seems to work much better. They will continue to use that same mix tomorrow with the new paver.

Printed 6/14/99 10:08:23 10:08:23

lowa Department of Transportation

Daily Report

*

			Contraction of the second second	998		TPU
81.0	Low Temperature	:	56.0			
	Sunset					
Cloudy						
	Cloudy	Sunset	Sunset	Sunset	Sunset	Sunset

ubcontractor	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen started to slip rail again with the new mix and paver at 8:15am. Things went very smooth and they poured 200+ cubic yards. John Adams, Mark Trueblood, and Mitch came out to the project today. Jensen is going to work tomorrow(Sat.) at 7am.

Printed 6/14/99 10:09:51 10:09:51

Daily 4 Page No.: Contract ID: 06/12/98 Fri Lay Sunrise: High: ate: Day: Sunset: Low: eather: in C. G. N. A's. Tohnston plant today. Mid morning. Checked F.A. dropped ... Fly has been increased and MAL. 17-57-6-10)... 10% wall didn't in 900d funea ano getting hroug WAS rier Stan E. arude. Charle hase plant Mark True blogo SDD to AUG K me mil design in a' epproved ic 1/2 was Kind. 10.000 throng sample By: <u>7</u> Date: 06/15/98 Sunrise: High: Sunset: Day: Low: Weather: 1.57-010 ... to go. Kanning with 6000 Mari lunt improvement. later this wee run good to go By: 74

lowa Department of Transportation

Daily Report

Contract No.	77-0353-069	Date : Sat	urday, June 13, 1998	Initials of Inspector:	TPU
High Temperatu	ure: 81.0	Low Temperature:	62.0		
Sunrise		Sunset			
Weather Comm	nent: Sunny				
Site Timechar	ge				
00	0				

bcontracte	or	
ID	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen began promptly at 7am. Only poured two sections which was about 107 cubic yards. Finished around noon. Things went very well. Barring any rain, they will start Mon. at 7am.

lowa Department of Transportation

Daily Report

Contract No. 77-0353-069	Date: Monday, June 15, 1998	Initials of Inspector: TPU
High Temperature: 70.0	Low Temperature: 58.0	
Sunrise	Sunset	
Weather Comment: Cloudy		
Site Timecharge		
00 1.000		
Subcontractor		

bcontracto ID	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen slipped rail today from 7am to 4:30pm, finished 4 sections. They will continue to use the new paver until they decide if they want to buy it or not. Rex Kinkade stopped today to run some air tests and take some sample cylinders.

Iowa Department of Transportation

Daily Report

High Temperature:	89.0 Low Temp		
	Representation and a second	erature: 65.0	
Sunrise	Sunset		
Weather Comment: Pt. 0	Cloudy		
Site Timecharge			
00 0			

ubcontracto ID	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen finished up slipping the rail today. Slipped 4.5 sections. They worked from 6:30am to 1:30pm. Jensen will hand pour the box outs Monday.

Inspector

lowa Department of Transportation

*

Daily Report

Contract No. 7	7-0353-069	Date :	Friday, June 19, 1998	Initials of Inspector:	TPU
High Temperature:	86.0	Low Temperature:	67.0		
Sunrise		Sunset			
Weather Comment:	Pt. Cloudy				
Site Timecharge					
00 1.000					
		an a			

Subcontracto	5	
ID	Name	Comment
Jensen	Jensen Road Co.	

Remarks:

Jensen slipped 6 sections of rail today. Worked from 7am to 7pm. Only 4.5 sections of rail left, they plan to finish up slipping tomorrow.

Inspector

Site 3 FORN 1E

Page____ of _____

DATE	WEATHER/COMMENTS
2-1-99	Clay Hamid Hi 26° Low 63°
Friday	Carlson Grading & Cleaning out 6 Median
	section placing " Expension to they Go.
	Winner Ruiting Intake tops (4 A Day)
	Jenson Setting String Line conduit and
	Steel getting ready to place Barrier Rail.
	Juesday July 5th Her said they could
	place 4,000' P- Day, Should just take 3'2 Days
	then instand of Zweeks which they Perdicted
	it would take
	tensen's told Winmar they would
	Pay the extra cost for them to use M-1
	to help then out with cure time.
	Informed Charlie Davis at Consons to
	Straighten Out temp Berrier Rail on West
	End of Project for this tong veckent because
	No eve will be Working.
	V
ENTERED BY:	R.

DATE	WEATHER/COMMENTS
12	Pt/v lidy Mild in Mill. Drove through checking on traffic Control and Storm Vater Discharge after Lost Nights Rein, talked to Charlie Davis he said they only poured the 2 Median sections under mother Stidge and 86th st. Buildge because of the Weather said they Stoped Paving at 9:00 or 9:30 m. Filled out Work Doy Pepert Left for home i
Sunda y	Clear Sunny Humit H: 89° Low 20° <u>Checked on traffic Control</u> this AM. <u>also Noted that Corlson aren't setting</u> <u>the Header Steel Bors in the 6'Median Sodies</u> <u>for the Inteles Very Streight will have to</u> <u>Cut them off and Redrill. Also the</u> <u>Steel for the 's Section of Barrier Rai'</u> <u>under the two Bridges is Not Very Streight</u> <u>Not d'out of Concrete Not 11'' from</u> <u>the Piero</u>
ENTERED BY:	 33

	FORN	1E
Page	of	

DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
7-4-94	Not Humid
Monday	Not Humid Holiday No Work.
	Clear in And Clayin PM. Hi 89° Low 74°
Tuesday	Jensen Placing Barrier Rail from Sto. 583 ± 55 + 593+80 583 ± 55 - Maxing slow in the Beginning but
	Picking up As day wards on
	Carlson Crew is cleaning up le' Median
	orea, setting Mastic getting ready for Paving
	Joints.
	Winnor Building Intokes Again today
	using M-4 at Jensen's Requesto
	Corlson, Peilly & the D.o.t. Are all that
	Attended our weekly Meeting today
	Corlson going to Pave 6 Median storting
	this Afternoon
	(Loztso) Dos Maines Asphalt Placing 3' temp Pasing
	(602+50) Des Moines Asphalt Placing 3' temp Pasing (602+50) at 2:30 pm today. Will probably get about 1/2 or 3/3
	of it takey and Maybe figish up tomorrow
	weather Permitting
NTERED BY:	24

FORN IE Page of ____ CONTRACT_ PROJECT NO.____ DIARY WEATHER/COMMENTS DATE ! 2-6-94 PHLy Clay Windy Humida H: 90° Low 74° Pouning ind 2 Wednesday Corlson Ra AN, Lic 1h Run 10 Heir Sent Plant Man G. 10 tasper Bernisz 0 × ner tra 10 runnin See Le ms fourrow Pasing . about 12:30 said Pare 2:00 a Li. their grades Jensens - 8:30 Barrier Starte hut * were 76-Low runnind No in hic 6 4 11/1 Desn lucar 11 MC he this MIHN :H 60 3 fest corre < ar a PM. teasen lown ENTERED BY :__

	FORM IE Page of
DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
2-2-94	Aly Clay Humid Hi 89° Low 64
	Winnor working on Intokes today
	Corlson Pasing 6' Modean
	Jensen Placing Median Parriar Rail. Still
¥	having problems with the Air, trying to Maintain
	6%
7.8-94-	PHLy Clay Mild II: 83° Low 68°
Friday	Winner building interes Again Loday will try and
	Pour either 4 or 5 at 3:00 PM
	Carlson's Paving crew should finish up
	with 6 Median by Noon on Maybe 10:00 today
	Jensen paving on Borrism Rail again today
	Still having Problem's with the Air. MP to
	80° vd. this P.M. Seat Somple of Air
	Agent to Amon for lesting it came back
	OK. Materials Engr. will be put Monday
	to check it out & fack to Contractor about
	what to do.
	æ.S.
ENTERED BY	

ENTERED BY:_____

	FORN	1 E
Page	of _	

PR	0	F	٢٦	• N	0	

DATE	WEATHER/COMMENTS
7-9-94	Ally Clay to Clear Hi 83° Low LeG°
Saturday.	Jensen's working on Placing
	conduit and tiering Steel for Barrier
	Rail. Also working in Mechine (Convender III)
	Slip Form Pover, Only North being done
	loder fillet out Por Voucher, Working
<u></u>	
	working on Reports.
2-11.94	Pt/x Cldy Humid Hi 88° tow 20°
	Jensons placing Borrier Rail this
	AM. First truck Left Plant air at
	6.8% Lest on grade at 5.5%. Informed
9	Plant of this, they Added 5th of Air and I gal
	of Water. Said they were going to
	Keep telding water until we reached a slump
	that would be workable. At 1:00 they switched back to the
	original Mix to try it again (0-57-6-C)
	Dick Mann and Champ Noration were present
	Loday to examin the Barrier Rail and the
	Process of Placing it to Maybe enhighten as
	on what we are doing wrong, and correct
	the Poplen.
	el
ENTERED BY:	37

	FORM	1 E
Page	of	

DATE	WEATHER/COMMENTS
7-11-94	Larry Strette and Rick Carleon
Monday	streed by the Project this P.M. osked
Continued	_ about the Barrier Rail
	Rick Said he would Call tim
	Rassmussen tonight and falk to him, Rick
	said the Borrier Rail is holding us back
	he want to switch traffic on 2-24-94
	+ which is only 2 weeks advey.
	Larry Skretta Left me their New
	Progress Report which I will give to horry
	Hill or Mitch Dillason
	their Mechine Broke Down about
	2:15 Herman Brown is suppose to be out
	to fix it will start again tonurrow morning
7-12-94	Cloudy Humid Hi 86° tow 65.°
tuesday	Jensens Placing Borrier Rail at 6:15 AM
	Air tested at 7.820 with a 5/8" Slump
	using a D-57 Mix this AM, with No
	Fly Ash Concrete reached tob site
	with a temperature of 92°. With No
	Fly Ash it appears to be sticking to
	the fins of the truck more
	But working better through Machine.
ENTERED BY:	()
	38

	FORM	IE
Page	of _	

DATE	WEATHER/COMMENTS
1-12-94	Held our Weekly meeting this AM (2:00)
tuesday	Present were Norm Larsau of Carlson Chris Reilly
Continued	Bob Reilly of Reilly Construction Shown Goodoo at
	In State Signing and A man from Att towns
	didn't get his Neme. Mitch Dillavon, Lorry
	Hill Phil Ketchum Mike Pagel and My solf from.
	the D.O.t. the Major concern was tensors
	Bannien Rail Operation. Champ Naratan also
	Attended the Meeting Introduced him as
	Dick Mumors Replacement to Dist Matts Fage.
	tri State will place their Glare
	Screen Monday as Wiser has to Extend
	t.B.R. after Reilly Removes Remainder of
	Median Barrier Roil which they Intend on
	doing this P.M. or tomorrow.
	All Towa says they can Point
	all of Moin Line in I day. But they
	have to remove alot of Vellow Edgelines
	and typer Sections
ENTERED BY:	R.
	20

	FORM IE Page of
DIARY	PROJECT NO CONTRACT
DATE	WEATHER/COMMENTS
1-13-94	! !
Wednes Jax	
	Every thing working Well lodox as they
	Placed 2300; then it Rained.
2-14-94	Ptly Clay mild Hi BI tow 62°
thursday	Barrier Rail Machine (Consuder III) Not working
	today wout track straight going forward but
	works great backing up. Working on Machine
••••••	want get started very early today.
	got 800' today Not good at all. Densen said they would Place the
	Barrier Rail with M-4 to speed up care time
	But were informed No M-4 because it
	shrinks to much would cause creating and fares
	Reillys Will Start Stark piling their
	Granular Subbase Material tonight
	at 100th st. North Side of Interstate
ENTERED BY	

	FORN	IE
Page	of _	

DATE	WEATHER/COMMENTS
2-15-94	Ptly Cldy Warn Fund H: 86° Low 65
Friday	Jensen Placing Borrier Rail this AM.
	Started at 7:30 Not Vory carly. Having transe
	with Vibrators again this AM Has a Man from
	Gamero Co. hore working on them.
	Reillys hould Granular Subbase.
	in and Stackpilet hast night will run
	gradation on it to certify Maderia as
	the Engineer doesn't Like his Method of
	Stack piling. He is using Belly Dumps over a
	Bridge then removing with Rubber fired End Loader
	driving up the pile contaminating the pile with
	Mud also causing seggration of Maderials.
	tenson said they will make the net
	St. Bridge tonight even it it is 10:00!
	Ames will not allow M-A to be
	placed in Barrier Rail except for the small
	gops over the Intokes.
ENTERED BY:	p.J.
	41

	FORM	1 E
Page	of	

DATE	WEATHER/COMMENTS
2-16-94	Cloudy Mild Lieti Chause Hi BI Low 62"
Saturday.	· · · · · · · · · · · · · · · · · · ·
	22" st. Bridge lotax as that is all the coment
	American has, which is only about 200'
	Lite Shower passing through at 2:00 A.M.
	contractor on hold till it Passes,
	Hod a Accident at 2:30 this AM & 16 Your
	old boy had been delivering papers, was reducing when
	he droped off South Edge of Slab, on returning
	wont across both Lones and hit our temp. Bernier Fail
	Called 911, Urbandala Police Responded Case
	No. 94-6799 on 7-16-94
->	Jenson's finished Barrier Rail to 7200
	Street Bridge at 12:30 PM. then went back
	and Poured Under 100th st. Bridge on the bast
	Bound Side of the Barrier Rail!
	Said they Might Form and Pour
	the rest of 100th st. gap tomorrows!
	· ·
ENTERED BY:	Q_


FORN IE Page____ of ____ CONTRACT_ PROJECT NO._____ DIARY WEATHER/COMMENTS DATE ! ptly Clay Wasm 1: 87° Low 12° 7-18-94 Showers Pi Monday Plans Main Jensen BARRIER Slip For 100 Gops Pour their 86 th st. Bridge Setting forms under this also getting Per Not-Pour Fast Rarrisa No 50 + 1:00 PM. Parcier work on Faps 10 4 2-19-94 PHLY CLAY Hot 91° 11. 1042 22 JENSEN Setting forms under 86th st. Bridge tuesday offer they man this P.M. 1 DOUR a tain -Not much Diud Au 10. 0015 -141 Carlson Meeting us Cind 1. M ina the re Merrich Goodyo Dase hawn Poilly of Railly Skredra and Norm 114 Lorry Conson! Phil Kerdum Mike irsin Dilavou My Soll. X1. 17 D.0%. sit. 15 (/ S Jensons Borrier Rail Milor Gucern aut switching troffic this West ENTERED BY:_

APPENDIX D Core Descriptions


POLK COUNTY PROJECT SITES AND CORE DESCRIPTIONS

- Core 1A, I-80, EBL MP 139.05, 20 ft. west - BAD
- Core 1B, I-80, EBL MP 139.05, 70 ft. west - GOOD
- Core 1C, I-80, EBL MP 140.06 - BAD
- Core 2A, I-35, I-80, WBL MP 132.9, 4 ft. east of drain panel - GOOD
- Core 2B, I-35, I-80, WBL MP 132.9, 54 ft. east of drain panel - GOOD
- Core 2C, I-35, I-80, WBL MP 132.9, 4 ft. west of drain panel - GOOD
- Core 2D, I-35, I-80, WBL MP 132.9, 24 ft. west of drain panel - GOOD
- Core 3A, I-35, I-80, WBL MP 128.25 - GOOD
- Core 4A, I-35, I-80, SBL MP 126.5 - GOOD
- Core 4B, I-35, I-80, SBL MP 126.5 - BAD


APPENDIX E Core Photos



Cores 1A, 1B and 1C




Barrier showing sites (dark 4" diameter circle) for core 1A



Barrier showing site (dark 4" diameter circle) for core 1B




Barrier showing site (gray 4" diameter circle) for core 1C




Cores 2A, 2B, 2C and 2D




Barrier showing site (dark 4" diameter circle) for cores 2A and 2C $\,$




Core 3A




Barriers showing site (dark 4" diameter circle) for core 3A



Cores 4A and 4B



Barrier showing site (gray 4" diameter circle) for core 4A



Barrier showing site (dark 4" diameter circle) for core 4B

APPENDIX F Core Analysis Tables

MLR-98-4 - Chloride Content Analysis 7-23-99 IOWA STATSuperQ Results Quantitative

SEQUENCE	CORE NUMBER	TEST DEPTH (IN.)	CHLORIDE (%)
1	1A	0.5	0.126
2	1A	1	0.044
3	1A	2.5	0.026
4	1B	0.5	0.222
5	1B	1	0.061
6	1B	2.5	0.032
7	1C	0.5	0.184
8	1C	1	0.058
9	1C	2.5	0.031
10	2A	0.5	0.021
11	2A	1	0.018
12	2A	2.5	0.015
13	2B	0.5	0.018
14	2B	1	0.014
15	2B	2.5	0.017
16	2C	0.5	0.022
17	2C	1	0.022
18	2C	2.5	0.017
19	2D	0.5	0.017
20	2D	1	0.025
21	2D	2.5	0.021
22	3A	0.5	0.167
23	3A	1	0.040
24	3A	2.5	0.021
25	4A	0.5	0.105
26	4A	1	0.037

Core # MP 1A 139.05 1B 139.05	4								-
		Location	Appearance	Depth	Air, %	Air, %	Dia.	Surface	Factor
				(in.)			(microns)	(mm-1)	(mm)
	139.05	20' w., EBL	Map cracking	0.5	1.40	0.84	369	16.260	0.609
				1.0	2.10	1.27	296	20.270	0.403
				2.5	2.60	1.58	350	17.143	0.428
		70' w., EBL	Okay	0.5	6.00	3.68	182	32.967	0.142
				1.0	5.60	3.43	183	32.787	0.149
				2.5	7.70	4.75	226	26.549	0.152
1C 140.06		EBL	Map cracking	0.5	7.10	4.37	222	27.027	0.157
				1.0	6.90	4.24	272	22.059	0.196
				2.5	7.90	4.87	354	16.949	0.235
2A 132.90	-	4' E. of drain panel, WBL	Okay	0.5	8.00	4.94	336	17.857	0.221
				1.0	8.90	5.51	366	16.393	0.226
				2.5	6.50	3.99	344	17.442	0.256
2B 132.90		54' E. of drain panel, WBL	Okay	0.5	8.30	5.13	327	18.349	0.210
				1.0	9.80	6.08	293	20.478	0.170
				2.5	7.00	4.30	258	23.256	0.184
2C 132.90		4' W. of drain panel, WBL	Okay	0.5	7.90	4.87	258	23.256	0.171
				1.0	9.30	5.76	333	18.018	0.200
	1			2.5	9.40	5.83	326	18.405	0.194
2D 132.90		24' W. of drain panel, WBL	Okay	0.5	8.60	5.32	348	17.241	0.219
		5		1.0	8.30	5.13	329	18.237	0.212
				2.5	8.50	5.25	364	16.484	0.231
3A 128.25		WBL	Okay	0.5	7.40	4.56	263	22.814	0.181
				1.0	9.50	5.89	273	21.978	0.162
				2.5	10.20	6.34	263	22.814	0.149
4A 126.50		SBL	Okay	0.5	7.80	4.81	277	21.661	0.185
				1.0	7.90	4.87	201	29.851	0.133

MLR-98-4 - Slipform Barrier Rail Cores I-80 Polk County

NOTE: Core 4B was too deteriorated for lab analysis.

APPENDIX G New Mix Design for Concrete Barrier Rail

Section 2513. Concrete Barrier

ADD the following new sentence to the first paragraph of Article 2513.01, Description: The provisions of Section 2403 shall apply.

ADD the following new paragraph to the end of Article 2513.01, Description:

The Contractor shall use only F-shape temporary concrete barrier rail on roadways with a posted speed limit greater than 45 mph. On any projects let on or after October 1, 2002 the Contractor shall use the F-shape temporary concrete barrier rail.

REPLACE the first sentence of the first paragraph of Article 2513.03, Concrete, with the following: Concrete shall be Class D concrete, unless otherwise specified in the contract documents.

REPLACE all of Article 2513.03, Concrete, with the following:

A. Precast

Concrete shall be as specified in Article 2513.03, Paragraph B, or as approved by the Engineer, and in accordance with Section 2403. The concrete shall be proportioned, mixed, placed, and cured in a manner that will produce the minimum compressive strength at the time designated, as specified below:

	Strength Before	
	Moving From	Strength At
	Casting Bed (psi)	Age 28 Days (psi)
Precast	1750	5000

Strength at Age 28 Days shall be reached before storing in multilayers or shipping.

The air content of fresh unvibrated concrete shall be 6.5 percent, as a target value, with a maximum variation of plus or minus 1.0 percent.

B. Cast-in-Place and Slip Form

Section 2403 shall apply, except the concrete shall meet the following mix design requirements:

- 1. Cement. Cement content shall be 603 pounds per cubic yard.
- 2. Water. The total mixing water and free moisture in the aggregate shall not exceed the following:

	Pounds of Water
	Per Pound
Class of Concrete	Of Cementitious Material
BR (Slip Form)	0.450
BR (Cast-in-Place)	0.480

 Aggregates. The combination of aggregates shall be uniformly graded in accordance with Materials I.M. 532, meeting the following gradation limits:

Sieve Size	Percent Passing
1 1/2 inch	100
3/4 inch	81-93
1/2 inch	67-79
3/8 inch	57-69
No. 4	41-53
No. 8	29-41
No. 16	21-33
No. 200	0-1.5

- 4. Admixtures. Air entrainment shall be used. The air content of fresh unvibrated concrete shall be 6.5 percent, as a target value, with a maximum variation of plus or minus 1.0 percent. To improve workability and aid in air entrainment, water reducing or retarding admixtures may be used in accordance with Article 2513.02, Paragraph C.
- 5. Fly Ash. The conditions and allowable rates of fly ash substitution shall be in accordance with Article 2301.04, Paragraph E. Article 2301.04, Paragraph F, shall also apply.

Class D concrete may be substituted and Section 2403 shall apply.

REPLACE all of Article 2513.09, Tolerances, with the following:

A newly fabricated unit of temporary barrier rail shall be free from honeycomb, surface spalling, and surface defects. Corner breaks and bottom spalls after shipping and placement shall not exceed 1 square foot of total surface area, which includes the base.

Other than honeycomb, shallow voids, not exceeding 3/4 inch diameter, which appear on the formed surface after proper consolidation will not be considered as surface defects and need not be filled unless they appear in an abnormal concentration.

A used unit of temporary barrier rail shall not have spalls, corner breaks, and bottom spalls totaling more than 5 square feet of surface area, which includes the base.

Connecting loops on all barrieres shall not be deformed and shall be true to dimensions.

Gaps between units shall not exceed the dimensions shown in the contract documents.

DELETE the third paragraph of Article 2513.11, Method of Measurement.

DELETE the second paragraph of Article 2513.12, Basis of Payment.