GALVANIZED BRIDGE DECK REINFORCING

FINAL REPORT FOR Iowa Department of Transportation Project HR-504

DECEMBER 1992

Highway Division

Iowa Department of Transportation



Final Report for Iowa Department of Transportation Project HR-504

Galvanized Bridge Deck Reinforcing

by

Chris Anderson 515-239-1392 Office of Materials Highway Division Iowa Department of Transportation Ames, Iowa 50010

December 1992

TECHNICAL REPORT TITLE PAGE

1.	REPORT NO.	2.	REPORT DATE
	HR-504		December 1992
3.	TITLE AND SUBTITLE	4.	TYPE OF REPORT & PERIOD COVERED
	Galvanized Bridge Deck Reinforcing		Final Report, 10-66 to 7-92
5.	AUTHOR(S)	6.	PERFORMING ORGANIZATION ADDRESS
	Chris Anderson, Technician 4 Materials Department		Iowa Department of Transportation 800 Lincoln Way Ames, Iowa 50010

7. ACKNOWLEDGEMENT OF COOPERATING ORGANIZATIONS

Construction Technology Laboratories, Inc. (CTL)

8. ABSTRACT

The deterioration of bridge decks due to steel corrosion is a problem encountered several years ago. This project, using galvanized reinforcement, began over twenty years ago. Since that time, epoxy coated reinforcement has become the specified material used in bridge decks.

The decks researched in this project are located on I-35 in Story County. They were constructed in 1967.

The results from the testing done on this project show that galvanizing protects steel from corrosion due to deicing salts, resulting in less/no concrete deterioration.

9. KEY WORDS

10. NO. OF PAGES

Galvanized reinforcement, Bridges, Corrosion, Reinforcing steel

TABLE OF CONTENTS

	Page
Introduction	1
Objective	. 1
Project Description	1
Materials	2
Construction	3
Testing	3
Discussion of Results	4
Summary	4
Conclusions	4
Acknowledgement	5
Appendices	
Appendix A - Steel Placement and Concrete Placement	6
Appendix B - Annual Test Results Appendix C - Construction Technology Laboratory Results	16 25

DISCLAIMER

The contents of this report reflect the views of the author and do not necessarily reflect the official views of the Iowa Department of Transportation. This report does not constitute any standard, specification or regulation.

INTRODUCTION

The corrosion of untreated reinforcing steel in bridge decks prompted this research over twenty years ago. At that time, untreated black steel was the primary reinforcement used. The corrosion of the untreated steel caused deterioration of the bridge decks. This was due to deicing salts penetrating the surface of the deck to the underlying steel. The steel would then corrode resulting in cracking and spalling of the concrete surrounding the steel in the bridge deck.

In this project galvanized reinforcement was used in part of the deck and compared to the conventional uncoated steel.

There were also some researchers who suggested that there would be adverse chemical reactions between the concrete and the galvanizing.

OBJECTIVE

The objective of this project was to determine the durability of a bridge deck constructed using galvanized reinforcing steel.

PROJECT DESCRIPTION

This project is located on I-35 over Long Dick Creek in Story County. There are two structures, one northbound and one southbound. The bridges are dual 193'-0 x 39' pretensioned prestressed concrete bridges with three spans of 64'-1", 64'-10" and 64'-1".

Each deck incorporated both untreated and galvanized steel. The deck of the southbound lane contained both transverse and longitudinal rebar of galvanized steel. The galvanized rebar are located only in the south half of the bridge and only the top layer of steel is galvanized. Galvanized tie wires were used in this section. The deck of the northbound bridge contains galvanized rebar for transverse steel only. These galvanized rebars were placed in the south half of the deck and were placed as the top layer of reinforcing steel. The north half of the deck used all untreated rebar. Uncoated tie wires were used in this deck. The figures in Appendix A show the placement of steel in both bridges. The depth of cover of the concrete over the galvanized steel reinforcement ranged from 2 1/2" to 5" with an average of 3" depth.

MATERIALS

In these bridge decks, No. 5, 6 and 7 bars were used. The coating thickness was checked on the galvanized bars before construction. The results are in Table I.

TABLE I

Spelter
<u>oz./ft.</u> ²
4.7
5.4
2.8

The galvanized coating thickness exceeds 1.2 oz./ft.² required by ASTM A-123.

The concrete mix design consisted of a cement factor of 710 lbs./cu.yd. and a water cement ratio of .40 to .41. The entrained air content ranged from 5.2% to 6.2%. NCHRP Report 23 noted that the concrete placement must be carefully supervised since it did represent a potentially large variable. A pictorial diagram of the location of each truck load of concrete was kept to show where it was placed and the slump and air in each location. This diagram is in Appendix A.

CONSTRUCTION

All regular construction field procedures were followed. More loads were tested so the construction of the deck could be documented. Rain occurred during the placement on the south span of the northbound bridge. This was documented in case scaling would eventually occur. No scaling, however, did occur in this section.

TESTING

The Iowa DOT performed electrical potential testing, obtained cores for chloride determination and checked for delaminations every other year. Those results are shown in Appendix B. Construction Technology Laboratories (CTL) completed testing in 1975, 1982 and 1991. They measured electrical potentials and water soluble chloride ion contents of concrete at the depth of embedded steel reinforcement. They also inspected the concrete deterioration, did petrographic examination to determine concrete quality, and metallographic analysis of galvanized coating. These results are in Appendix C.

DISCUSSION OF RESULTS

The results of the tests performed on these bridge decks showed that galvanized reinforcement showed little evidence of corrosion. There was no direct correlation of concrete deterioration related to corrosion of embedded steel reinforcement. It is also possible that any corrosion that did occur could have occurred before or immediately after placement of concrete.

SUMMARY

Based on some researchers' findings in the past, it is believed that galvanized steel develops sacrificial expansion products resulting in concrete deterioration. This has not proven true in this instance. Recent research has not uncovered any significant long term problems with galvanized reinforcement. Galvanized steel was at a disadvantage at first because both mats had to be galvanized, while with epoxy, only the top layer of steel was required to be coated. Approximately 4 years ago epoxy coated steel was also required on both layers because of transverse cracking which allows deicing salt brine to reach the bottom layer. From this and other studies that have been completed, it appears galvanized reinforcement has proven to be an effective method of preventing corrosion in bridge decks.

CONCLUSIONS

 Galvanized reinforcement on this bridge provided satisfactory resistance to corrosion with a 2 1/2" or greater cover.

 The galvanized reinforcement caused no problems on this bridge deck.

ACKNOWLEDGEMENT

The author wishes to express appreciation to Brian G. Stejskal of Construction Technology Laboratories and Dick Smith who has retired from the Iowa DOT for developing material used in this report. Appendix A Steel Placement and Concrete Placement Test Results







figure 3



Layout of Bridge Deck Sections

Figure 4

2 · ·



Distance in Feet





South Bound Lanc





Section 4 - Slump & Air Content



Section 5 Slump and Air Content



Appendix B Annual Test Results

Iowa DOT Project HR-504

IA-66-01

Galvanized Bridge Deck Reinforcing

- I-35 Northbound over Long Dick Creek
 Delamination Nil
 Curbs badly deteriorated
- I-35 Southbound over Long Dick Creek 2 sq. ft. Delaminated in shoulder area 5 sq. ft. Spalled in shoulder area

I-35 over Long Dick Creek Story County

.

193' x 39' Dual Prestressed Concrete Beam Bridge Constructed 1967

November 1977-All corrosion readings were less than 0.30 volt

- Test Section Locations



1

Bridge: I-35 over Long Dick Creek - Story County

.

CHLORIDE CONTENT - LBS/CU. YD.

-

Year		Sample D	epth (Inche	es)	
Sampled	0 - 0.75	0 - 1	0.75-1.5	r	1.5 - 2.25
1973					
S bound		3.86	_	_	1.78
		5.10	-	-	3.40
N bound		3.78	-	-	3.21
ł		3.40	-	_	1.40
1974					
S bound		2.46	-	-	0.96
		3.64	-	-	0.83
N bound		2.03	-	-	0.94
		1.30	-	-	0.88
1075					
1975 Chaund		0 1			
S bound			-	-	0.5
N bound		2.5	-	-	0.5
		2.4	-	_	0.7
		2.4	_	_	0.0
1976					
S bound		5.2	_	_	0.5
		4.8	_	_	0.6
N bound		1.8	-	-	0.4
		8.3	-	-	0.5
1977					
S bound	7.45	-	0.48	-	0.33
	9.22	-	1.01	-	0.55
	9.53	-	2.15	-	0.52
	11.34	-	1.78	-	3.03
N bound	16.75	-	4.69	-	1.03
	5.18	-	1.03	-	0.70
	,7.79	-	1,.35	-	0.55
1070					
TALA E poins	0 01		0 45		0.42
a nound	0.01	_	0.45	-	0.42
N bound	8.28	_	1.97	-	0.42
	4.20	_	1.97	_	0.64

Bridge: 1-35 over Long Dick Creek - Story County

CHLORIDE CONTENT - LBS/CU. YD.

Year		Sample D	epth (Inche	es)	
Sampled	0 - 0.75	0 - 1	0:.75-1.5	· · · · · · · · · · · · · · · · · · ·	1.5 - 2.25
1981					
S bound	13.19	-	8.35	-	0.56
	10.28	-	3.63	_	0.68
N bound	5.93	-	0.30	-	0.49
	5.07	-	0.95	_ ·	0.30
1					
		•			
					[[
		1			
-					
}					

Bridge: I-35 Northbound over Long Dick Creek

CHLORIDE CONTENT - LBS/CU. YD.

Year	Year Sample Depth (Inches)					
Sampled	0 - 0.5	0.5 - 1	1 - 1.5	1.5 - 2	2 - 2.5	
1983	11.87 14.44 9.68 6.13 7.11 5.56 5.86	4.95 4.23 2.95 1.66 1.06 1.44 0.15	1.13 0.60 1.40 0.45 0.38 0.53 0.30	0.34 0.57 0.53 0.26 0.30 0.42 0.30	0.42 0.49 0.38 0.19 0.53 0.53 0.30	
1985	9.03 10.09 11.26 11.23 3.21 4.23	3.89 0.64 5.10 3.33 1.17 1.06	1.32 2.19 1.32 0.91 0.79 0.72	0.76 0.71 0.30 1.78 0.42 0.68	0.49 0.49 0.38 0.76 0.68 0.45	
1987	8.20 4.91 10.51 5.03 5.82 4.61 6.50	5.52 1.66 4.57 2.15 1.70 0.49 0.95	1.40 0.87 3.67 1.74 0.83 0.57 0.57	0.53 0.64 1.13 1.51 0.45 0.45 0.57	0.53 0.45 0.87 1.51 0.45 0.57	
1989	13.08 6.54 15.76 8.69 10.47 10.96	6.16 2.65 11.72 1.63 2.65 3.40	3.67 1.25 8.69 0.87 1.51 1.13	1.40 1.13 4.80 0.87 0.87 0.64	0.76 0.76 0.38 0.87 0.76 0.76	

Ţ



Bridge: _____I-35 Southbound over Long Dick Creek - Story County

CHLORIDE CONTENT - LBS/CU. YD.

	Sample D	epth (Inche	es)	
0 - 0.5	0.5 - 1	1 - 1.5	1.5 - 2	2 - 2.5
13.23 7.64 14.33 12.13 13.95 12.55	6.54 1.59 11.60 0.76 3.36 3.67	1.51 0.30 2.61 0.26 0.60 1.29	0.45 0.45 0.26 0.45 0.23 0.38	0.76 0.64 0.26 0.45 0.30 0.60
8.51 13.65 7.52 14.18 26.99 11.68	2.76 1.44 2.72 7.98 14.82 0.64	0.68 0.83 0.83 7.98 9.19 0.57	0.57 1.06 0.64 0.57 2.72 0.57	0.53 0.46 0.60 0.64 0.30
10.09 6.12 10.77 4.23 15.08 9.60 11.64 12.74	3.97 1.51 0.91 0.64 3.78 5.67 1.44 1.70	1.02 0.64 0.23 0.45 0.95 0.83 0.49	0.49 0.76 0.83 0.45 0.30 0.38 0.38 0.53	0.68 0.38 0.49 0.57 0.87 0.30 0.45 0.64
	$\begin{array}{r} 0 - 0.5 \\ 13.23 \\ 7.64 \\ 14.33 \\ 12.13 \\ 13.95 \\ 12.55 \\ 8.51 \\ 13.65 \\ 7.52 \\ 14.18 \\ 26.99 \\ 11.68 \\ 10.09 \\ 6.12 \\ 10.77 \\ 4.23 \\ 15.08 \\ 9.60 \\ 11.64 \\ 12.74 \end{array}$	Sample D 0 - 0.5 0.5 - 1 13.23 6.54 7.64 1.59 14.33 11.60 12.13 0.76 13.95 3.36 12.55 3.67 8.51 2.76 13.65 1.44 7.52 2.72 14.18 7.98 26.99 14.82 11.68 0.64 10.09 3.97 6.12 1.51 10.77 0.91 4.23 0.64 15.08 3.78 9.60 5.67 11.64 1.44 12.74 1.70	Sample Depth (Inche $0 - 0.5$ $0.5 - 1$ $1 - 1.5$ 13.23 6.54 1.51 7.64 1.59 0.30 14.33 11.60 2.61 12.13 0.76 0.26 13.95 3.36 0.60 12.55 3.67 1.29 8.51 2.76 0.68 13.65 1.44 0.83 7.52 2.72 0.83 14.18 7.98 7.98 7.98 7.98 26.99 14.82 9.19 11.68 0.64 0.57 10.09 3.97 1.02 6.12 1.51 0.64 10.77 0.91 0.23 4.23 0.64 0.45 9.60 5.67 0.95 11.64 1.44 0.83 12.74 1.70 0.49	Sample Depth (Inches) $0 - 0.5$ $0.5 - 1$ $1 - 1.5$ $1.5 - 2$ 13.23 6.54 1.51 0.45 7.64 1.59 0.30 0.45 14.33 11.60 2.61 0.26 12.13 0.76 0.26 0.45 13.95 3.36 0.60 0.23 12.55 3.67 1.29 0.38 8.51 2.76 0.68 0.57 13.65 1.44 0.83 1.06 7.52 2.72 0.83 0.64 14.18 7.98 7.98 0.57 16.69 0.64 0.57 0.57 10.09 3.97 1.02 0.49 6.12 1.51 0.64 0.76 10.77 0.91 0.23 0.83 4.23 0.64 0.45 0.45 15.08 3.78 0.45 0.30 9.60 5.67 0.95 0.38 11.64 1.44 0.83 0.38 12.74 1.70 0.49 0.53

.



Appendix C Construction Technology Laboratory Results

Section A.2: IOWA STRUCTURE



Identification:

Two bridges on I-35 over Long Dick Creek (Story County) located near Ames, Iowa. The dual concrete decks service northbound and southbound traffic and are supported by two piers.

Year of Construction: 1967

Age: 24 years

Description:

The subject structure is a dual 3-span bridge which was previously inspected in 1981. All three spans of both decks were included for study. The bridge decks measure approximately 193 x 39 ft each and are composed of prestressed concrete beams spanning 64 to 65 ft. Reinforced concrete decks are constructed with both treated and galvanized steel reinforcing bars, as indicated on the next page.

-A.14-

Detail of Steel Reinforcement:

The north halves of both decks are constructed with untreated steel reinforcement in the longitudinal and transverse direction. The top mat in the south half of the concrete deck servicing southbound traffic contains galvanized longitudinal and transverse steel bars. Galvanized steel reinforcement is secured with galvanized steel wires. The top mat in the south half of the northbound deck contains galvanized transverse steel, and untreated longitudinal steel bars. Standard uncoated tie wires were used in this section of the bridge deck. The bottom steel reinforcing mats in both northbound and southbound decks are constructed with untreated steel bars.

Concrete Mix Design:

Cement Factor:	710 lbs/cu yd (7.55 bags/cu yd).
Water-to-Cement Ratio:	0.40 to 0.41 (4.5 to 4.6 gal/bag)
Air Content:	5.2 to 6.2%

Electrical Potentials:

Electrical potential survey results are presented in Figs. A.2.(a - f). Areas of similar potential are defined by equipotential lines at 100 millivolt intervals. Electrical potential measurements were recorded on a 5 ft. grid pattern.

Surface Defects:

Concrete deterioration in the form of cracking was observed on exposed deck surfaces. Concrete cracking oriented in the transverse direction is shown in Figs. A.2.(g - i). In some instances, cracks occur over embedded steel reinforcement.

Subsurface Delaminations:

Sounding of concrete decks indicated minor subsurface delaminations and small unbonded surfaces at isolated areas.

Chloride Analysis:

Water-soluble chloride content analysis of 12 concrete powder samples removed from the subject decks was performed. Tests were conducted in accordance with ASTM C 144 and analysis performed by potentiometric titration with silver nitrate. Results of tests are summarized in Table A.2.

-A.15-

Petrographic Examination:

Eight concrete core samples were removed from the concrete decks at locations designated as L-1, L-2, L-4, L-6, L-10, L-11, L13, and L-14. The location and description of core samples taken for study are presented in Table A.2. Petrographic examinations were performed on three of the cores (L-6, L-10, and L-14) to evaluate the condition and quality of concrete in respective deck slabs. Petrographic examinations were performed on the core samples in accordance with ASTM Designation C 856-83. Results of the examinations indicated the following:

Core Designation	Depth of Carbonation (inch)	Estimated Water/Cement Ratio	Air-Entrainment	Air Content
L-6	0.10	0.50 to 0.55	Air-Entrained	4 to 6%
L-10	0.10	0.45 to 0.50	Air-Entrained	3 to 5%
L-14	0.10	0.50 to 0.55	Air-Entrained	4 to 6%

Cores L-10 and L-14 exhibited vertical cracks and corrosion on steel reinforcement (reference Table A.2). In addition, microcracking was observed around chert and dolomitic chert, which are reactive fine aggregates that can cause internal concrete deterioration.

Metallographic Measurements:

- <u>Core L-6</u>: Core sample contained a single reinforcing bar (No. 6) with a galvanized coating which averaged 3.8 mils thick. The coating structure consists of a blocky delta layer and a columnar growth of zeta crystals which are covered with a layer of pure zinc (eta layer). The smooth surface of the coating suggests that the sample has experienced only minimal corrosion attack.
- <u>Core L-10:</u> Core sample shows a direct comparison between a coated bar (No. 5) and an uncoated steel bar (No. 6). The slightly ragged surface profile of the galvanized coating indicated that slight attack has taken place, although the coating still averages approximately 4.7 mils thick. The uncoated bar, which has a greater depth of concrete cover than the galvanized bar exhibits red rusting over almost half of its length.

28

-A.16-

<u>Core L-14</u>: Core sample contained two uncoated reinforcing bars(No. 5 and No. 6). Both of the bars appeared to be in good condition.

Core	Bar Size	Depth of Concrete Cover	Galvanized Coating Thickness
Designation		(inches)	(mils)
L-6	No. 6	3	3.8
L-10	No. 5	3-1/4	4.7
	No. 6	4-7/8	(Uncoated)
L-14	No. 5	2-1/2	(Uncoated)
	No. 6	3-1/4	(Uncoated)

The following is a summary of the metallographic examination:

.

Table A.2: CONCRETE CORE AND POWDER SAMPLE SUMMARY

AMES BRIDGE, IOWA

CONCRETE CORE DESCRIPTIONS:

ł

1

: .

.

CTL CORE DESIGNATION	LOCATION	STEEL REINFORCEMENT	DEPTH OF CONC. COVER (inches)	COMMENTS
L-6	SOUTH SPAN	No. 6 Bar	3"	No Corrosion Detected
	(N.B. LaneS)	No. 7 Bar	3-7/8"	(Same)
L-10	SCUTH SPAN	No. 6 Bar	3-1/4"	No Corrosion Detected
	(S.B. Lanes)	No. 7 Bar	4-7/8"	Crack, Corrosion Detected
L-13	MIDDLE SPAN	No. 7 Bar	2-5/8*	Crack, No Corrosion
	(S.B. Lanes)	No. 5 Bar	3-1/4"	No Corrosion Detected
L-14	NORTH SPAN	No. 6 Bar	2-1/2"	Light Corrosion Detected
	(S.B. Lanes)	No. 6 Bar	3-1/4"	(Same)

CHLORIDE ION TEST RESULTS:

CTL Powder Designation	SPAN (Lanes)	Depth of Powder Sample (inches)	Electro-Potential Readings (MV)	Water-Soluble Chloride Content
L1A	MIDDLE (N.B.)	2-1/4 to 2-3/4	170	0.257
L2	NORTH (N.B.)	2-1/4 to 2-3/4	135	0.057
L3A	NORTH (N.B.)	2-1/2 to 3	60	0.043
L4A	SOUTH (N.B.)	2-1/4 to 2-3/4	135	0.086
L5A	SOUTH (N.B.)	2-1/4 to 2-3/4	135	0.036
L6A	SOUTH (N.B.)	2-1/4 to 2-3/4	370	0.171
L7A	SOUTH (S.B.)	2-1/4 to 2-3/4	370	0.186
L8A	NORTH (S.B.)	2-1/4 to 2-3/4	360	0.343
L9A	SOUTH (S.B.)	2-1/4 to 2-3/4	300	0.193
L11	SOUTH (S.B.)	2-1/2 to 3	70	0.057
L12	SOUTH (S.B.)	1-1/2 to 2-1/4	120	0.714
L13	MIDDLE (S.B.)	2-1/4 to 2-3/4	60	0.121

* Based on an estimated cement content of 14%

(by weight of cement)







Iowa Department of Transportation AMES, IOWA (Story County) DISTRICT 3

AMES BRIDGE (I-35 over Long Dick Creek) FIG A.2(a)

CTL 050324

Construction Technology Laboratories, Inc.

Λ	\sum
Kr	

	-400mV	-300) MV	-200)mV	-100)mV	n0	۱V	
Y										

(NORTH END OF BRIDGE)



Iowa Department of Transportation AMES, IOWA (Story County) DISTRICT 3

AMES BRIDGE (I-35 over Long Dick Creek) FIG A.2(b)

CTL 050324

Construction Technology Laboratories, Inc.

\wedge	
	\neg

.

(NORTH END OF BRIDGE)



Iowa Department of Transportation		FIG A.2(c)
DISTRICT 3	(I-35 over Long Dick Creek)	CTL 050324



-400m	V	-300)mV	-200	νmγ	-100	ŊmV	01	ן ∨י
									E

(NORTH END OF BRIDGE)

		198	•0		•	•	•		•	•	104	225	
262	204	123	105	\$3	194	146	149	128	123	133	284	180	
,	•	•	•	•	•	•	•	•	•	•	•	•	
184	207	119	108	83	147	123	125	115	184	128	108	181	
,	•	•	•	•	•	•	•	•	•	•	•	•	_
150	100	144	103	137	158	129	123	125	151	121	165	137	
	•	•	•	•	•	•	•	•	•	•	•	•	Northbound
181	137	114	78	77	103	**	78	114	112	49	140	112	Lanes
,	•	•	•	•	•	•	•	•	•	•	•	•	201100
284	150	119	97	126	114	••	127	125	109	119	10.8	138	
											•		
	173	155	142		•	120		175	130	112	94	154	
117	184	133	124	136	113	157	108	105	85	76	"	189	
	•	•	•	•		•	•		•				
<u></u> 113	187	94	59	27	_ 30	72	91		58	43	24.		
,	•	•	•	•	•	•	•	•	•	•	•	•	
164	101	110	85	3.0	84	45	105	67	59 .	78	110	75	
,	•	•	•	•	•	•	•	•	•	•	•	•	
123	85	100	102	72	7.8	100	120	44	21	40	363	172	
	•	·	•	•	•	•	•	•	•	•	•	•	
76.0		71	4.	41	62		83	.7	21	e o	128	17	>
	•										•		Southbound
.00	113	8 0 •	72	48	100	**	116	• 7	• 7 •	•7	140	•7	Jamaa
					••								Lanes
			20	•	72		132	40		*	145		
77	50		•	•	•	•	•						
77 '	50 • 100	20 • 7	•	15	45	•	15	12	30		••	70	
177 1 1 8	50 • 100	20 • •	3	• 15 •	• 45 •	, 42 ,	15	12	30	••	••	70 •	
177 118 150	50 • 100 • 40	20 • • 10	3 10	15 13	• 45 • 11	, 42 , 12	• 15 • 17	12 • 2	30 35	** • 34	•• • 110	70 • 115	

(SOUTH END OF SPAN)

NORTH SPAN

Iowa Department of Transportation AMES, IOWA (Story County) DISTRICT 3

AMES BRIDGE (I-35 over Long Dick Creek) FIG A.2(d)

CTL 050324

Construction Technology Laboratories, Inc.

÷

-	400m	V	-300)mV	-200	λwΛ	-10	QmV	01	nV
		Na katalan kata Na katalan kata								日

(NORTH END OF BRIDGE)

	123	143	218	213	228	205	180	228	185	303	202	208	
					392	164	130	• • •	144	380	340	172	
	124	174	140			110	142						
		•	•	•	•	•	•			•			_
2	136	173	160	148	151	142	128	74		100	123	107	
•	•	•	•	•	•	•	•	•	•	•		.	Northbound
190	190	155	198	198	132	124	94	82	234	131	104	116	Lanaa
•	•	·	•	•	·	•	•	•	•	•	•	•	Lanes
399	238	152	169	217	135	157	313	155	137	181	287	144	
•	•	•	•	•	•	•	•	. •	•	•	•	•	
310	186	185	131	186	152	14.4	183	141	146	154	144	183	
•	•	•	•	•	•	•	•	•	•	•	•	•	
264	357	45	184	109		101	154	161	193	209	291	218	
. 7	278	138	77	29	9.8	9.2		44	121	24.4	105		
•	•	•	•	•	•		•		•		105		
28	151	105	43		68	112	82	35	103	118		1	
•	•	·	·	•	•	٠	•	•	•	•	•	•	
• 3	183	150	59	66	84	194	107	78	116	182	117	155	
•	•	•	•	·	•	•	•	•	•	•	•	•	
4.6	87	54	91	35	34	58	79	• 2		78	108	100	·>
•	•	•	•	·	•	•	•	•	•	•	•	•	Southbound
• •		48		75	24	30	87	85	44	72		•3	Southbound
					-	-		·	·	•	·		Lanes
• •	40	14	44	27	•	**	30	42		60	17	43	
									•	·	•		
r.) 1	2		54	••	•	106	•	71	44	191	21	40	
		••			••								
			_						-			_	

(SOUTH END OF SPAN)

MIDDLE SPAN

Iowa Department of Transportation AMES, IOWA (Story County) DISTRICT 3

AMES BRIDGE (I-35 over Long Dick Creek) FIG A.2(e)

CTL 050324

Construction Technology Laboratories, Inc.

5. I

1 ¹

-400mV	-300mV	-200mV	-100mV	0mV
-			<u> </u>	
ł				

(NORTH END OF BRIDGE)

	333	269	188	254	• •	133	251	164	248	227	179	284	
215	236	247	273	215	74	136	103	85	173	193	186	260	
	•	•	•	•	•	•	•	•	•	•	•	•	
209	236	203	212	70	94	71		122	121	118	117	371	
		•		•							•		~
	•		•		•	•		•	•	•	•	•	Northboun
29	173	161	174	158	102	92	85	61	109	151	151	367	Lanes
	•	•	•	•	•	•	•	•	•	•	•	•	Lunco
208	141	282	167	132	103	165	94	91 •	138	97	138	180	
	150	202	85	143	••	112	52	132	81	114	112	220	
•	•	•	•	•	•	•	•	•	•	•	•	·	
	235	114	4.7									***	
3.	,		•			•							
36	93	149	148	52	100	210	•	130	• • 1	285	351	245	
36	93	149	148	52	100	210		130	•1	285	351	246	
136	93	149 125	148	52	100	210	• 0 • 0 • 2 • 1	130	• • • • • • • • • • • • • • • • • • •	285	351	246 246 294	
135	93 • • • • •	149 • 125 •	148 • • •	52 52 47	100 - 30 110	210 145	• • • • • • •	130 • 130 • 127 • 192	• • • • •	265 • • •	351 173	245 245 294 315	
135	93 180 	149 • 125 • 182	148 • • • • • • • •	52 52 47	100 - 30 + + + + +	210 145	* * * * * * * * *	130 130 - 127 - 197 -	* *1 * 70 * *	265 	351 • 173 •	245 294 315	
138 135 143 268	93 180 	149 125 182	148 • • • • • • • •	52 52 47 72	100 - 30 110 - 75	210 	47 33 43 47 47 53	130 130 127 192	91 - 70 - 62 - 34 -	265 	351 - 173 - 88 - 82 -	245 245 294 315 292	>
135 135 143 268	93 180 368 152 129	149 - 125 - 182 - 104 - 76	148 • • • • • • • • • • • • • • • • • • •	52 52 47 72 98	100 - 38 + 110 - 75 - 50	210 - - - - - - - - - - - - - - - - - - -	80 62 47 63 111	130 - 127 - 192 - 19 - 19	• • • • • • • • • • • • • • • • • • •	265 82 49 72	351 - 173 - 88 - 82 - 121	294 294 315 292 292	Southbound
135	93 93 180 388 152 129	149 - 125 - 182 - 104 - -	148 • • • • • • • • • • • • • • • • • • •	52 52 52 47 72 98	100 - 38 - 110 - 75 - 50 -	210 210 145 182 182 182 182 182	80 47 47 47 47 47 47 47 47 47 47 47 47 47	130 - 127 - 192 - 192 - 192 - - - - - - - - - - - - - - - - - - -	• • • • • • • • • • • • • • • • • • •	285 285 82 89 72 89	351 	200 246 294 315 292 292	Southbound Lanes
138 135 143 268 117 5 5 5 5	93 180 388 152 129 248	149 - 125 - 162 - 104 - 76 - 57 -	148 148 152 152 152 152 152 152 152 152 152 152	52 52 47 72 96 60	100 - 38 - 110 - 50 - 50 -	210 210 145 162 31 75 29	5	130 	• • • • • • • • • • • • • • • • • • •	265 	351 	246 294 315 292 229 235	Southbound Lanes
135 143 268 117 15 139	93 93 180 368 152 129 248 112	140 - 125 - 182 - 104 - 76 - 57 - 60	148 148 152 68 53 21 97	200 52 52 47 72 96 52 47 52 47 52 47 52 52 52 52 52 52 52 5	100 - 3 - 110 - 7 5 - 50 - - 31	145 145 162 31 75 29 52	5 6 6 6 6 7 7 6 5 7 7 8 3 7 111 - 38 - 40	130 130 130 130 130 130 140 0 14 14 173	• • • • • • • • • • • • • • • • • • •	265 - - - - - - - - - - - - - - - - - - -	351 - 173 - 88 - 82 - 121 - 105 -	246 284 316 292 229 235 276	Southbound Lanes
135 143 268 117 5 139	348 348 348 348 348 348 348 348 348 348	149 - 125 - 182 - 104 - 57 - 60 -	148 148 148 152 152 155 152 152 152 152 152	52 52 47 72 98	100 - 30 - 110 - 50 - 50 - 31 -	145 145 145 162 1 210 145 162 1 210 210	5 6 6 6 6 6 7 6 7 6 7 6 7 6 7 6 7 7 6 7 7 7 7 7 7 7 7 7 7	130 130 130 130 130 130 130 130	• • • • • • • • • • • • • • • • • • •	205 	351 	200 246 254 315 292 229 235 278	Southbound Lanes

(SOUTH END OF SPAN)

SOUTH SPAN

Iowa Department of Transportation AMES, IOWA (Story County) DISTRICT 3

AMES BRIDGE (I-35 over Long Dick Creek) FIG A.2(f)

CTL 050324

Construction Technology Laboratories, Inc.

1



(NORTH END OF BRIDGE)



Construction Technology Laboratories, Inc.



Iowa Department of Transportation AMES, IOWA (Story County) DISTRICT 3

AMES BRIDGE (I-35 over Long Dick Creek) FIG A.2(h)

CTL 050324

Construction Technology Laboratories, Inc.

ł



Construction Technology Laboratories, Inc.

40



PHOTOS A.2(a & b):

j

Representative Conditions of Bridge Deck Wearing Surface (Note areas of concrete deterioration and ashalt patch shown in Photo b)

-A.19-



PHOTOS A.2(c & d):

Close-up Views of Core Sample L-1 Note that the water-soluble chloride ion content in powder sample L-1A was 0.257 (by weight of cement), at a depth of approximately 2-1/2-in. Potential survey results indicated a reading of -170 mv in adjacent concrete.



PHOTO A.2(e):

Steel samples removed from Core Sample L-6.



PHOTO A.2(f): Magnification of No. 6 Bar removed from Core Sample L-6 (galvanized coating thickness of 3.8 mils).

-A.21-

43



PHOTO A.2(g): Steel samples removed from Core Sample L-10.



PHOTO A.2(h): Magnification of No. 5 Bar removed from Core Sample L-10 (galvanized coating thickness of 4.7 mils).

-A.22-

*

44



PHOTO A.2(i): Steel samples removed from Core Sample L-14.



PHOTO A.2(j): Magnification of No. 6 Bar removed from Core Sample L-14 (steel reinforcement is uncoated).

PETROGRAPHIC EXAMINATION OF HARDENED CONCRETE, ASTM C 856

CTL PROJECT NO.: 154070 CLIENT: International Lead Zinc Research Organization STRUCTURE: Bridge Deck LOCATION: Ames, Iowa DATE: January 22, 1992 PROBLEM: Quality Evaluation EXAMINED BY: L. Powers-Couche

Page 6 of 25

SAMPLE:

Identification: L6.

Dimensions: Diameter = 4.0 in.; Length = 4.0 to 5.0 in.

Top Surface: Abraded surface with exposed coarse aggregate. Aggregate particles are polished and stand out in relief against softer paste.

Bottom Surface: Broken surface fractured around aggregate.

Cracks, Joints, Large Volds: Many areas of underconsolidation. The largest underconsolidated area is 1.5 in. long and 2.0 in. wide.

Reinforcement: No. 6 rebar is located 3.0 in from top surface.

AGGREGATES (A)

Coarse (C): Siliceous and calcareous gravel consisting of granite, limestone, chert, altered volcanic rock (hematitic and silicified), and schist.

Fine (F): Siliceous and calcareous sand consisting of quartzite, quartz, limestone, chert, feldspar, schist, hornblende, granite, graywacke, and hematite-cemented sandstone.

Gradation & Top Size: Evenly graded to a top size of 0.7 in.

Shape & Distribution: CA is rounded to subangular, equidimensional to elongate, and somewhat nonuniformly distributed. FA is rounded to subangular, equidimensional, and uniformly distributed.

PASTE

Color: Medium gray.

Hardness: Moderately hard.

Luster: Subvitreous.

Calcium Hydroxide*: 7 to 10% uniformly distributed small crystals.

Unhydrated Portland Cement Clinker Particles (UPC's)*: 8 to 12% uniformly distributed UPC's and relics.

Depth of Carbonation: 0.1 in. from top surface.

Air Content: 4 to 6% uniformly distributed, small, spherical air voids and irregularly shaped, larger (up to 0.5 in.) paste-lined, entrapped air voids.

Fly Ash*: None observed.

Paste-Aggregate Bond: Moderately tight. The concrete breaks around the smooth, hard coarse aggregates.

Secondary Deposits: Inwardly-pointing ettringite needles line or fill voids.

*percent by volume of paste

1

1

1

Microcracking: No significant microcracks are observed.

ESTIMATED WATER-CEMENT RATIO: 0.50 to 0.55.

MISCELLANEOUS: Chert particles have dark rims, however, no other evidence of alkali-silica reaction is observed. The paste is carbonated around limestone particles and around some larger air voids.

PETROGRAPHIC EXAMINATION OF HARDENED CONCRETE, ASTM C 856

CTL PROJECT NO.: 154070 CLIENT: International Lead Zinc Research Organization STRUCTURE: Bridge Deck LOCATION: Ames, Iowa DATE: January 22, 1992 PROBLEM: Quality Evaluation EXAMINED BY: L. Powers-Couche

Page 8 of 25

SAMPLE:

Identification: L10.

Dimensions: Diameter = 4.0 in.; Length = 6.5 in.

Top Surface: Abraded surface with coarse aggregates exposed. Aggregates are polished and stand out in relief against softer paste.

Bottom Surface: Irregular, broken surface fractured through aggregates.

Cracks, Joints, Large Voids: The concrete is generally well consolidated with no visible joints and few voids larger than 0.2 in. Two major vertical cracks which mostly pass around aggregates pass lengthwise through the core.

Reinforcement: No. 5 rebar is located 3.2 in. from the top surface. No 6 rebar is 5.0 in. for the top and is corroded.

AGGREGATES (A)

Coarse (C): Siliceous and calcareous gravel consisting of granite, limestone, chert, altered volcanic rock (hematitic and silicified), and schist.

Fine (F): Siliceous and calcareous sand consisting of quartzite, quartz, limestone, chert, feldspar, schist, hornblende, granite, graywacke, and hematite-cemented sandstone.

Gradation & Top Size: Evenly graded to a top size of 0.7 in.

Shape & Distribution: CA is rounded to subangular, equidimensional to elongate, and somewhat nonuniformly distributed. FA is rounded to subangular, equidimensional, and uniformly distributed.

PASTE

Color: Medium gray.

Hardness: Moderately hard.

Luster: Subvitreous.

Calcium Hydroxide*: 6 to 8% uniformly distributed small crystals and patches. Calcium hydroxide lines voids and partially coats aggregates.

Unhydrated Portland Cement Clinker Particles (UPC's)*: 10 to 15% uniformly distributed UPC's and relics.

Depth of Carbonation: 0.1 in. from top surface.

Air Content: 3 to 5% uniformly distributed, small, spherical air voids.

Fly Ash*: None observed.

Paste-Aggregate Bond: Moderately tight.

Secondary Deposits: Blades of calcium hydroxide and ettringite needles line or fill voids.

*percent by volume of paste

Microcracking: Microcracks occur around reactive chert particles. Other cracks are randomly oriented and pass through aggregates. Adjacent paste is carbonated.

ESTIMATED WATER-CEMENT RATIO: 0.45 to 0.50.

MISCELLANEQUS: Dark rims occur around chert and dolomitic chert. Adjacent paste is cloudy and isotropic. Curved cracks following the outline of the aggregate are also observed. Gel is seen in one crack and in several voids.

PETROGRAPHIC EXAMINATION OF HARDENED CONCRETE, ASTM C 856

CTL PROJECT NO.: 154070 CLIENT: International Lead Zinc Research Organization STRUCTURE: Bridge Deck LOCATION: Ames, Iowa DATE: January 22, 1992 PROBLEM: Quality Evaluation EXAMINED BY: L. Powers-Couche

Page 10 of 25

SAMPLE:

Identification: L14.

Dimensions: Diameter = 4.0 in.; Length = 5.6 in.

Top Surface: Moderately abraded surface with coarse aggregates exposed and polished.

Bottom Surface: Broken surface fractured through aggregates.

Cracks, Joints, Large Voids: Generally well consolidated with no visible joints. Some underconsolidation occurs around rebar. Air voids are typically smaller than 0.15 in. One side of the core intersected a vertical crack from the top of the core to a depth of 3 in. The crack passes through several coarse aggregate particles.

Reinforcement: Corroded No. 6 rebar is located 2.5 in. from top of core, and corroded No. 5 or 6 rebar located 3.3 in. from top.

AGGREGATES (A)

Coarse (C): Siliceous and calcareous gravel consisting of granite, limestone, chert, altered volcanic rock (hematitic and silicified), and schist.

Fine (F): Siliceous and calcareous sand consisting of quartzite, quartz, limestone, chert, feldspar, schist, hornblende, granite, graywacke, and hematite-cemented sandstone.

Gradation & Top Size: Evenly graded to a top size of 0.7 in.

Shape & Distribution: CA is rounded to subangular, equidimensional to elongate, and somewhat nonuniformly distributed. FA is rounded to subangular, equidimensional, and uniformly distributed.

PASTE

Color: Medium gray.

Hardness: Moderately hard.

Luster: Subvitreous.

Calcium Hydroxide*: 7 to 10% uniformly distributed small crystals.

Unhydrated Portland Cement Clinker Particles (UPC's)^o: 8 to 12% uniformly distributed UPC's and relics.

Depth of Carbonation: 0.1 in. from top surface.

Air Content: 4 to 6% uniformly distributed, small, spherical air voids and irregularly shaped, larger (up to 0.5 in.) paste-lined, entrapped air voids.

Fly Ash*: None observed.

Paste-Aggregate Bond: Moderately tight. The concrete breaks around the smooth, hard coarse aggregates.

^{*}percent by volume of paste

Secondary Deposits: Blades of calcium hydroxide and ettringite needles line or fill voids.

Microcracking: Microcracks occur around reactive chert particles. Other cracks are randomly oriented and pass through aggregates. Adjacent paste is carbonated.

ESTIMATED_WATER-CEMENT_RATIO: 0.50 to 0.55.

MISCELLANEOUS: Dark rims occur around chert and dolomitic chert. Adjacent paste is cloudy and isotropic. Curved cracks following the outline of the aggregate are also observed. Gel is seen in one crack and in several voids.

Table B.2(a): CONCRETE POWDER SAMPLE SUMMARY (1975 CTL Report)

CTL Powder	Electro-Potential	Water-Soluble	Water-Soluble	Water-Soluble
Designation	Readings	Chloride Content	Chloride Content	Chloride Content*
	- (-MV)	(Ibs/cu yd concrete)	(by weight of concrete)	(by weight of cement)
SF2				
O" TO 1/4"	N.A.	13.80	0.352	2.518
3/4" TO 1"	N.A.	3.60	0.092	0.657
1-1/2" TO 1-3/4"	N.A.	0.70	0.018	0.128
SF3				
O" TO 1/4"	N.A.	14.50	0.370	2.646
3/4" TO 1"	N.A.	1.40	0.036	0.255
1-1/2" TO 1-3/4"	N.A.	0.70	0.018	0.128
SF5				
O" TO 1/4"	N.A.	4.30	0.110	0.785
3/4" TO 1"	N.A.	1.60	0.041	0.292
1-1/2" TO 1-3/4"	N.A.	0.70	0.018	0.128
NG1				
O" TO 1/4"	NA	4 20	0 107	0 766
3/4" TO 1"	N.A.	1.40	0.036	0.255
1-1/2" TO 1-3/4"	N A	0.50	0.000	0.233
NC2	11.2	0.50	0.013	0.031
NG3		0.00	0.000	
O* TO 1/4*	N.A.	9.00	0.230	1.642
3/4" TO 1"	N.A.	1.30	0.033	0.237
1-1/2" TO 1-3/4"	N.A.	0.50	0.013	0.091
NG5				
O" TO 1/4"	N.A.	3.50	0.089	0.639
3/4" TO 1"	N.A.	1.40	0.036	0.255
1-1/2" TO 1-3/4"	N.A.	0.70	0.018	0.128
NN2				
O" TO 1/4"	N.A.	10.70	0.273	1.952
3/4" TO 1"	N.A.	7.90	0.202	1.441
1-1/2" TO 1-3/4"	N.A.	0.40	0.010	0.073
NN4				
0" TO 1/4"	N.A.	4.20	0.107	0.766
3/4" TO 1"	N.A.	0.80	0.020	0.146
1-1/2" TO 1-3/4"	N.A.	0.40	0.010	0.073
NN5				
Q* TO 1/4*	NA	2 30	0.059	0 420
3/4" TO 1"	NA	0.60	0.000	0.100
34 10 1	N.A.	0.00	0.015	0.109

AMES BRIDGE, IOWA

* Based on an estimated cement content c* *4*,

(by weight of cement)

Depth at Which Sample	Lbs. Cl ^{-/} cu. yd. of Concrete at Location Indicated								
Was Taken	SF2	SF3	SF5	NG1	NG3	NG5	NN2	NN4	NN5
$\begin{array}{r} 0 & - & 1/4 \\ 3/4 & - & 1 \\ 1-1/2 & - & 1-3/4 \\ 2-1/4 & - & 2-1/2 \\ 3 & - & 3-1/4 \end{array}$	13.8 3.6 0.7 0.6* 0.6	14.5 1.4 0.7 0.7* 0.5	4.3 1.6 0.7 0.4* 0.5	4.2 1.4 0.5 0.6 _*	9.0 1.3 0.5 0.5*	3.5 1.4 0.7 0.3*	10.7 7.9 0.4 0.7* 0.4	4.2 0.8 0.4 0.4* 0.3	2.3 0.6 0.4 0.2* 0.2

TABLE 8 - RESULTS OF CHLORIDE ANALYSES

*Denotes level of top steel at location indicated.

TABLE 9 - RESULTS OF PH MEASUREMENTS

Depth at Which Sample	pH at Location Indicated								
Was Taken	SF2	SF3	SF5	NG1	NG3	NG5	NN2	NN4	NN5
0 - 1/4" $3/4" - 1"$ $1-1/2" - 1-3/4"$ $2-1/4" - 2/1/2"$ $3" - 3-1/4"$	12.3 12.4 11.9 11.2* 11.3	12.1 11.8 11.8 11.7* 11.8	12.4 12.0 11.8 11.8* 11.9	12.2 12.1 12.0 12.0 -*	12.2 12.1 12.0 12.0*	12.4 12.1 12.1 12.1* -	12.2 12.0 9.2 11.8* 11.7	12.3 12.1 12.1 12.0* 11.7	12.3 12.2 12.0 12.0* 11.5

*Denotes level of top steel at location indicated.



← NB



SB 🛶

.

.

Fig. 21 - Diagram showing cover over top transverse reinforcing bars.

٠.





Potentials are expressed in millivolts.

Fig. 22 - Diagram of distribution of electrical potentials in top mat of reinforcing steel.

SB-





CTL Powder Designation		Electro-Potential Readings (-MV)	Water-Solubie Chioride Content (Ibs/cu yd concrete)	Water-Soluble Chloride Content (by weight of concrete)	Water-Soluble Chloride Content* (by weight of cement)	
LD-1	М	90	1.44	0.037	0.263	
LD-2	М	370	0.56	0.014	0.102	
LD-3	Ν	100	0.64	0.016	0.117	
LD-4	s	350	0.88	0.022	0.161	
LD-5	s	120	0.92	0.023	0.168	
LD-6	s	120	0.44	0.011	0.080	
LD-7	s	240	0.20	0.005	0.036	
LD-8	s	40	0.96	0.025	0.175	
LD-9	м	10	0.92	0.023	0.168	
LD-10	s	110	0.64	0.016	0.117	
LD-11	s	150	0.56	0.014	0.102	
LD-12	s	70	0.76	0.019	0.139	
LD-13	М	80	0.40	0.010	0.073	
LD-14	Ν	100	0.40	0.010	0.073	
LD-15	Ν	100	0.92	0.023	0.168	

AMES BRIDGE, IOWA

į

Table B.2(b): CONCRETE POWDER SAMPLE SUMMARY (1982 CTL Report)

* Based on an estimated coment content of 14%

(by weight of cement)

Sample No.	Sample Depth, in.	Steel Mat	Potential- Volts	Cl ⁻ content lbs/cu yd	Average Coating Thickness Remaining Mils *
LD-1 LD-2 LD-3 LD-4 LD-5 LD-6 LD-7 LD-8 LD-9 LD-10 LD-11 LD-12 LD-13 LD-14 LD-15	2-1/4 - 2-3/4 $2 - 2-1/2$ $2 - 2-1/2$ $2-1/4 - 2-3/4$ $2-3/4 - 3-1/4$ $2-1/2 - 3$ $2 - 2-1/2$ $2 - 2-1/2$ $2-3/4 - 3-1/4$ $2 - 2-1/2$ $2-1/4 - 2-3/4$ $2-3/4 - 3-1/4$ $2 - 2-1/2$ $2-1/2 - 3$ $2-1/2 - 3$ $2-1/4 - 2-3/4$	Untreated Untreated Galv. & Untr. Galv. & Untr. Galv. & Untr. Galvanized Galvanized Galvanized Galvanized Galvanized Galvanized Untreated Untreated	$\begin{array}{r} -0.09 \\ -0.37 \\ -0.10 \\ -0.35 \\ -0.12 \\ -0.12 \\ -0.24 \\ -0.04 \\ -0.01 \\ -0.11 \\ -0.15 \\ +0.07 \\ -0.08 \\ -0.10 \\ -0.10 \end{array}$	1.44 0.56 0.64 0.88 0.92 0.44 0.20 0.96 0.92 0.64 0.56 0.76 0.40 0.40 0.92	- - 7.7 5.8 5.7 - - - 5.4 - 6.1 - -

Table 1 - Results of Chloride and Metallographic Measurements

*Based on average of 10 readings

_



Fig. 1 Diagrams of Ames Bridge for Northbound Traffic Showing Results of Potential Measurements, Crack Survey, and Locations of Test Samples.

٠.



Fig. 2 Diagrams of Ames Bridge for Southbound Traffic Showing Results of Potential Measurements, Crack Survey, and Locations of Test Samples.

· '.

59

``~