

A d d e n d u m

Iowa Department of Transportation
Office of Contracts

Date of Letting: January 16, 2013
Date of Addendum: January 15, 2013

B.O.	Proposal ID	Proposal Work Type	County	Project Number	Addendum
152	35-0356-120	HMA RESURFACING WITH MILLING	Franklin	MP-003-2(704)172--76-35 IMX-035-6(120)166--02-35 IMX-035-8(46)217--02-98	16JAN152.A04

Notice: Only the bid proposal holders receive this addendum and responsibility for notifying any potential subcontractors or suppliers remains with the proposal holder.

Make the following change to the Proposal Schedule of Prices:

Add Proposal Line No. 0781 2524-6765014 REMOVE AND REINSTALL MILEPOST
MARKER, 10.000 EACH

Add Proposal Line No. 0782 2524-6765015 REMOVE AND REINSTALL DELINEATOR
POSTS, 269.000 EACH

Add Proposal Line No. 1141 2524-6765014 REMOVE AND REINSTALL MILEPOST
MARKER, 10.000 EACH

Add Proposal Line No. 1142 2524-6765015 REMOVE AND REINSTALL DELINEATOR
POSTS, 269.000 EACH

If the above changes are not made, they will be made as shown here.

Make the following change to the plans for Project No. IMX-35-6(120)166--02-35:

Tab. 100-4A ESTIMATE REFERENCE INFORMATION:

Add the following note to the reference notes for the item 2524-6765014 REMOVE
AND REINSTALL MILEPOST MARKER:

Any damaged Mile Post shall be repaired or be replaced by the contractor with no
additional cost. Special care to post placement, so mile post marking on post shall be
correct with the location on post.

Method of Measurement shall be for each Milepost removed for other operational
requirements.

Basis of payment shall be for material, equipment and labor for each Milepost removed,

all posts reinstalled with adjustments (because of new Guardrail installations), and repair of any removal damage.

Add the following note to the reference notes for the item 2524-6765015 REMOVE AND REINSTALL DELINEATOR POSTS:

Any damaged beyond repair will be replaced by the contractor with no additional cost. Special care to post placement, so mile post marking on post shall be correct with the location on post.

Method of Measurement shall be for each Delineator removed for other operational requirements.

Basis of payment shall be for material, equipment and labor for each Delineator removed, all posts reinstalled with adjustments (because of new Guardrail installations), and repair of any removal damage.

Add to TAB 105-4. SI-171 10-20-09 Reference Posts

Make the following change to the plans for Project No. IMX-35-6(46)217--02-98:

Tab. 100-4A ESTIMATE REFERENCE INFORMATION:

Add the following note to the reference notes for the item 2524-6765014 REMOVE AND REINSTALL MILEPOST MARKER:

Any damaged Mile Post shall be repaired or be replaced by the contractor with no additional cost. Special care to post placement, so mile post marking on post shall be correct with the location on post.

Method of Measurement shall be for each Milepost removed for other operational requirements.

Basis of payment shall be for material, equipment and labor for each Milepost removed, all posts reinstalled with adjustments (because of new Guardrail installations), and repair of any removal damage.

Add the following note to the reference notes for the item 2524-6765015 REMOVE AND REINSTALL DELINEATOR POSTS:

Any damaged beyond repair will be replaced by the contractor with no additional cost. Special care to post placement, so mile post marking on post shall be correct with the location on post.

Method of Measurement shall be for each Delineator removed for other operational requirements.

Basis of payment shall be for material, equipment and labor for each Delineator removed,

all posts reinstalled with adjustments (because of new Guardrail installations), and repair of any removal damage.

Add to TAB 105-4. SI-171 10-20-09 Reference Posts