

# A d d e n d u m

Iowa Department of Transportation  
Office of Contracts

Date of Letting: May 21, 2013  
Date of Addendum: April 26, 2013

<b>B.O.</b>	<b>Proposal ID</b>	<b>Proposal Work Type</b>	<b>County</b>	<b>Project Number</b>	<b>Addendum</b>
013	70-0929-141	BRIDGE REPAIR	MUSCATINE	BRFN-092-9(125)--39-70 BRFN-092-9(141)--39-70	21MAY013.A01

---

Notice: Only the bid proposal holders receive this addendum and responsibility for notifying any potential subcontractors or suppliers remains with the proposal holder.

---

Make the following change to the Proposal Attachment for Project No. BRFN-092-9(125)--39-70:

Replace Sheet 2 of 4 with the attached Sheet 2 of 4.

**For Bridge No. 7075.7S092:****Estimate Reference Information for 2427-0686010 Bridge Cleaning**

"Remove all accumulated foreign material in the approach and main spans from the following areas:

- a. Deck surfaces within 3 feet of curbs.
- b. Top of deck expansion joints (do not disturb neoprene seals).
- c. Deck drain inlets and drain pipes.
- d. Abutment backwalls and seats and bearings.
- e. Tops of piers at deck joints including bearings.
- f. Steel and concrete girders within 15 feet of deck expansion joints in concrete and steel spans approaching the truss span.
- g. Vertical and diagonal chords of truss below a plane located 15 feet above the deck surface.
- h. Bottom chords of truss (outside and inside). No standing water shall remain inside the bottom chords.
- i. End 5 feet of lateral bracing attached to bottom chords of trusses, including the gusset plates.
- j. End 5 feet of transverse floor beams in truss spans.
- k. Steel within 15 feet of centerline of bearings at each end of truss, including drain troughs under finger joints.
- l. The inside of the end post(member L0-U1) from the connection to the lower chord to the connection to the upper chord at all four corners of the bridge.

It also includes washing these elements with water under pressure."

"The accumulated foreign material shall be removed prior to washing with water under pressure."

**ADD: Top and Bottom handhole covers of the bottom chord shall be removed during washing.**

**Care should be made to not remove any nest of any migratory bird during this operation.**