

## Iowa Department of Natural Resources

### 2018 Summary Information Underground Storage Tanks (USTs)

#### General Information

Public Record Posted Date: 11/26/2018

Total Number Of UST Facilities: 2535

Total Number Of USTs: 7712

#### Summary Information For On-Site Inspections

Number Of UST Facilities Inspected: 1075

Inspection Period Dates: 10/1/2017 To: 9/30/2018

Percent Compliance (Combined Measure): 55%

#### Summary Information For Releases

Number Of Confirmed UST Releases: 28

Release Reporting Period Dates: 10/1/2017 To: 9/30/2018

Note: Tank, facility, and on-site inspection information is based on underground storage tanks in operation and inspected during federal fiscal year 2018. On-site inspections measure compliance with federal and state regulations for operating underground storage tanks.

Source			Cause													
			Spill		Overfill		Phys/Mech		Corrosion		Install		Other		Unkown	
#	%		#	%	#	%	#	%	#	%	#	%	#	%	#	%
<b>Tank</b>	2	7%							2	7%						
<b>Piping</b>																
<b>Dispenser</b>	4	14%					4	14%								
<b>STP</b>																
<b>Delivery</b>																
<b>Other</b>	22	79%													22	79%
<b>Totals</b>	28	100%					4	14%	2	7%					22	79%

# = number, % = percent of total number of releases

Note: Release, source, and cause information is based on releases from underground storage tanks regulated by the Iowa Department of Natural Resources.